

EXTERIOR ENVELOPE - CONSTRUCTION KEY NOTES CLEAN, REPAIR & REPOINT GRANITE MASONRY PER SPECIFICATIONS 04.08 REMOVE PLANT GROWTH 04.10 REPAIR CRACKED STONE 04.11 REPAIR HOLES IN STONE AT REMOVED FASTENERS 04.12 RESET BALLUISTRATE CAP CORNER STONE THAT APPEARS TO BE LOOSE 04.13 AFTER CONFIRMING WITH OWNER THAT IT IS NOT REQUIRED, REMOVE METAL POST ANCHORED TO TOP OF BALLUSTRADE CAP REMOVE DISLOCATED GRANITE CAPSTONE. REINFORCE BY RESETTING WITH STEEL PINS (REFER TO DETAIL INDICATED) CLEAN, REPAIR AND REPOINT HISTORIC GLAZED TERRACOTTA UNIT MASONRY PER 04.19 SPECIFICATIONS METAL COPING INSTALL NEW COPING TO CONCOURSE ROOF EDGE W/ SCUPPERS AND DOWNSPOUTS 05.13 REMOVE EXISTING DECORATIVE STEEL LINTEL AND RECONSTRUCT HORIZONTAL MULLION - REFER TO DETAIL INDICATED STANDING SEAM ROOF 08.03 WOOD WINDOW REFURBISHED PER SPECIFICATIONS - TYPICAL 08.07 EXIST WINDOWS AND STORM PANELS TO REMAIN INTACT 09.01 | METAL SPANDREL PANELS & WINDOW PANES, REFURBISHED PER SPECIFICATIONS -D 26.01 REMOVE SURFACE MOUNTED LIGHT FIXTURE, WIRING AND CONDUIT FOR LIGHTING TO FACILITATE REROOF REMOVE SURFACE MOUNTED CONDUIT SERVING EXTERIOR LIGHTING AND ALL ASSOCIATED FASTENERS D 26.03 REMOVE SURFACE MOUNTED SLOTTED CHANNEL FRAMING SUPPORTING EXISTING

ELEVATION NOTES

- REFER TO SHEET 1.GO.03 FOR NEW WORK GENERAL NOTES APPLICABLE TO THE ENTIRE PROJECT
- REFER TO SHEETS 1.A7.801 & 1.A7.802 FOR WINDOW RESTORATION SCHEDULES CONTAINING
- EXISTING WINDOW CONDITION REFER TO 1.A7.803 FOR REPLACEMENT WINDOW SCHEDULE
- REFER TO SHEET 1.A7.811 FOR WINDOW TYPES


EXTERIOR LIGHTING

- REFER TO SHEET 1/A7.815 FOR DOOR TYPES
- NEW WORK IS NOT TO DISTURB THE EXISTING VIDEO SURVEILANCE SYSTEM
- NOTES IDENTIFYING REQUIRED REPAIRS TO MASONRY AND TERRACOTTA CLADDING HAVE BEEN MADE WITH THE AID OF LIMITED SITE VISITS AND EXAMINATION OF DRONE PHOTOGRAPHY AND ARE NOT INTENDED TO BE COMPREHENSIVE. ANY CRACKS WIDER THAN 1/8" THAT TELEGRAPHS
- THROUGH MASONRY MATERIAL SHOULD BE REPAIRED PER SPECIFICATIONS. REPAIR STONE MASONRY PER SECTION 040342
- REPAIR ALL CRACKS
- PATCH ALL ABANDONED FASTENER HOLES. RESET ALL LOOSE STONES
- REPOINT STONE MASONRY PER SECTION 040343
- REPAIR HISTORIC TERRA COTTA UNIT MASONRY PER SECTION 040326
- REPAIR ALL CRACKS PATCH ALL CHIPPED UNTS CLEAN AND REPOINT HISTORIC TERRA COTTA UNIT MASONRY PER SECTION 040327
- IN ADDITIONS TO ADDRESSING AESTHETIC CONCERNS, REPAIR AND REPOINTING OF HISTORIC TERRA COTTA UNIT MASONRY IS TO BE PERFORMED TO THE EXTENT THAT WATER DOES NOT GET
- BEHIND UNITS REPAIR BRICK MASONRY PER SECTION 040322
- REPOINT BRICK MASONRY PER SECTION 040323 CLEAN DECORATIVE METAL PER SECTION 050371

ELEVATION LEGEND



AREA OF MASONRY WITH EXCESSIVE STAINING -REMOVE BIOLOGICAL AND OTHER TYPES OF STAINS



AREA OF MASONRY REQUIRING REPAIR - REFER TO KEYNOTE FOR MORE INFORMATION

H

Revisions Passenger Corporation (Amtrak), Office of Engineering, and is supplied on a confidential basis solely for use in connection with the design and construction of Amtrak facilities and equipment. The reproduction, display, sale or other disposition of this document without the express written consent of the National Railroad Passenger Corporation,

Office of Chief Engineer STRUCTURES National Railroad Passenger Corporation 30th Street Station, Philadelphia, Pennsylvania 19104

PENN STATION PARTNERS, LLC 1300 Thames Street, Suite 10 Baltimore, MD 21231 United States Tel 410.123.4567 Fax 410.123.4567

100 North Charles Street, 14th Floor Baltimore, MD 21201

Tel 410.576.0440

1300 North 17th Street, Suite 1000

Arlington, VA 22209

BALTIMORE

MARYLAND **HEADHOUSE REHABILITATION EXTERIOR ENVELOPE - EARLY RELEASE**


Designed Designer Drawn Author Checked Checker Date 10/9/20

60% SUBMISSION DRAFT


Sheet name: PARTIAL EAST ELEVATION


Work Elem. No: C.RE.100048


1.A2.603



FILE NAME: 1.A2.60








EXTERIOR ENVELOPE - CONSTRUCTION KEY NOTES

CLEAN, REPAIR AND REPOINT HISTORIC GLAZED TERRACOTTA UNIT MASONRY PER

SPECIFICATIONS

ELEVATION NOTES

- REFER TO SHEET 1.GO.03 FOR NEW WORK GENERAL NOTES APPLICABLE TO THE ENTIRE PROJECT
- REFER TO SHEETS 1.A7.801 & 1.A7.802 FOR WINDOW RESTORATION SCHEDULES CONTAINING
- **EXISTING WINDOW CONDITION** REFER TO 1.A7.803 FOR REPLACEMENT WINDOW SCHEDULE
- REFER TO SHEET 1.A7.811 FOR WINDOW TYPES
- REFER TO SHEET 1/A7.815 FOR DOOR TYPES
- NEW WORK IS NOT TO DISTURB THE EXISTING VIDEO SURVEILANCE SYSTEM
- NOTES IDENTIFYING REQUIRED REPAIRS TO MASONRY AND TERRACOTTA CLADDING HAVE BEEN MADE WITH THE AID OF LIMITED SITE VISITS AND EXAMINATION OF DRONE PHOTOGRAPHY AND ARE NOT INTENDED TO BE COMPREHENSIVE. ANY CRACKS WIDER THAN 1/8" THAT TELEGRAPHS
- THROUGH MASONRY MATERIAL SHOULD BE REPAIRED PER SPECIFICATIONS. REPAIR STONE MASONRY PER SECTION 040342
- REPAIR ALL CRACKS
- PATCH ALL ABANDONED FASTENER HOLES.
- C. RESET ALL LOOSE STONES REPOINT STONE MASONRY PER SECTION 040343
- REPAIR HISTORIC TERRA COTTA UNIT MASONRY PER SECTION 040326 A. REPAIR ALL CRACKS PATCH ALL CHIPPED UNTS
- CLEAN AND REPOINT HISTORIC TERRA COTTA UNIT MASONRY PER SECTION 040327
- IN ADDITIONS TO ADDRESSING AESTHETIC CONCERNS, REPAIR AND REPOINTING OF HISTORIC TERRA COTTA UNIT MASONRY IS TO BE PERFORMED TO THE EXTENT THAT WATER DOES NOT GET **BEHIND UNITS**
- REPAIR BRICK MASONRY PER SECTION 040322
- REPOINT BRICK MASONRY PER SECTION 040323 CLEAN DECORATIVE METAL PER SECTION 050371



PARTIAL NORTH ELEVATION AT CONCOURSE 1 PARTI. 1,A2.608 1/8" = 1'-0"

Key Plan
$C \rightarrow $
(E)
H

Revisions Passenger Corporation (Amtrak), Office of Engineering, and is supplied on a confidential basis solely for use in connection with the design and construction of Amtrak facilities and equipment. The reproduction, display, sale or other disposition of this document without the express written consent of the National Railroad Passenger Corporation, Office of Engineering, is prohibited.

Office of Chief Engineer STRUCTURES National Railroad Passenger Corporation 30th Street Station, Philadelphia, Pennsylvania 19104

Approved	Date	PENN STATION	
		PARTNERS, LLC	
		1300 Thames Street, Suite 10	三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三三
		Baltimore, MD 21231 United States	E
		United States	100 North Charles S
		Tel 410.123.4567	Baltimore, MD 21201
		Fax 410.123.4567	Tel 410.576.0440



115])	Seal/s		
WSP USA 1300 North 17 th Street, Suite 1000			

Arlington, VA 22209

MARYLAND BALTIMORE **HEADHOUSE REHABILITATION EXTERIOR ENVELOPE - EARLY RELEASE**

Sheet name:
PARTIAL NORTH ELEVATION AT
CONCOURSE

60% SUBMISSION DRAFT Checked Checker Date 10/9/20 1.A2.608

Work Elem. No: C.RE.100048

